

## CERTIFICATION by CUSTODIAN of RECORDS

2/3/14

Tucson Police Department Crime Laboratory 1306 W. Miracle Mile, Tucson, AZ 85705

I hereby certify that these documents are a true and correct copy of the			
periodic maintenance* for the Intoxilyzer 8000 Serial Number			
80-006051 maintained by the Tucson Police Department			
Crime Laboratory pursuant to the requirements of the Arizona Department			
of Public Safety for a quality assurance program.			
or I don't carety for a quarity assurance program.			
A quality assurance specialist (QAS) tested the instrument on the following			
dates. The acceptable accuracy limits, as defined in A.A.C. R13-10-104.A.2,			
for a 0.100AC solution are 0.090AC to 0.110AC.			
Date: 1.26.2016 Cal 1 AC Cal 2 AC			
Between the dates of and			
the instrument was operating properly and accurately.			
The instrument was taken out of service for repair on 1.26.2016.			
The instrument was taken out of service for repair on 1.26.2016.  The instrument was returned to service on			
Λ			
Sluy Callegn			
Terry S. Gallegos			
1 2 2 2 4 4			
1.27-2016			
ADPS QAS Permit # 33169			
274			
SUBSCRIBED AND SWORN to before me this 27th, day of			
January, 20/16.			
V .			
- Lling Locarcege			
Notary Dublic			
Notary Public OFFICIAL SEAL			
*Includes documents specified in A.A.C. R13-10-104.A.5			
FIMA COUNTY			
My Comm. Exp. Nov. 3, 2019			



## TUCSON POLICE DEPARTMENT CRIME LABORATORY

## INTOXILYZER SERVICE RECORD

Date: 1-26-2016	
QAS: Terry Gallegos	28847
Intoxilyzer Serial Number:	80-006051
	"System fault #018 Contact CMI"  "xilyzer to the Lab For more tests.  data and sent it to CMI for repair
Date Out of Service: [-26. 2016	
Calibration Check completed prior to remo	oval from service
Date:	
SQAP completed prior to removal from se	rvice
Date:	
Corrective Action:	Sent to CMI, Inc.



2052

This form MUST be completed and enclosed with instrument to be serviced.

Note: Please ship items in their original shipping container.			
Contact information: Customer Number 105075 (contact Customer Service)  Name TERRY GALLEGOS Phone: (520) 837-7673  Fax: (520) 791-4642 Email: TERRY. GALLEGOS TUCSONA?	<u>†</u>		
Bill to Address:  FINANCE/ACCOUNTS PAYABLE  PO BOX 27450  TUCSON, AZ 85726-7450  Ship to Address:  TUCSON POLICE DEPARTMENT  1306 W. MIRACE MILE  TUCSON, AZ 85705	CRIMELAE		
Instrument Serial Number: 80 -006051			
Detailed Description of Problem:  Display System fault #018 Confact CMT" and it failed these  Diagnostics: EEProm, DSP, Analytical test.  ***Hazardous Material Warning! - DO NOT return gas cylinders with instrument! ***  Note: An evaluation fee of \$39.50 for handheld instruments or \$79.00 for IR evidential instruments will apply to estimates which are not repaired.  I Authorize Repairs Up To: All \$250 \$500 \$750 Other \$  Purchase Order Number 37768			
Authorized By:  TERRY GALLEGOS TOXICOLOGY COORDINATOR Ship to:  Name (Please Print)  Title  CMI, Inc.  Attn: Service Dept.  316 East Ninth Street  Owensboro, KY 4230  No, please send estimate before repairs are made. An estimate will be faxed before performance.	3		
any repairs and may cause delays in service.	- ····· <b>J</b>		